


FP03-0255-00






Fig.3

	RECEPTION INTENSITY (dB)	50	09	20	06	06	10	22	55		
4	OWNER NO.	77734	77734	77734	77734	77735	77735	28777	77735		
	UPDATE TIME	2002/10/11-23:11	2002/10/11-23:11	2002/10/11-23:10	2002/10/11-23:11	2002/10/11-23:20	2002/10/11-23:20	2002/10/11-23:15	2002/10/11-23:16		
	LOCATION CODE	33331	00000	33332	50001	50001	00000	50010	55540		
	AGGREGATION LOCATION POINT NO. CODE	0005	0005	0003	0004	0004	0010	0012	0015		
	ID NO.	12345	12346	12347	12347	12348	12348	12349	12350	••	

4

Fig.5

4

LOCATION	LOCATION INFORMATION							
CODE	ECONTION IN ORIVIATION							
00000	UNDEFINED							
33331	FIRST FLOOR AT HOME OF USER A (ENTERED BY USER)							
33332	FIRST FLOOR AT HOME OF USER A (ENTERED BY USER)							
50001	FIRST FLOOR AT OFFICE OF USER B (ESTIMATED)							
50010	SECOND FLOOR AT OFFICE OF USER B (ESTIMATED)							
55540	FIRST FLOOR AT FACTORY OF USER B (ESTIMATED)							
:	:							
:	:							

Fig.6

	43
	V
AGGREGATION	LOCATION
POINT NO.	CODE
0001	00000
0002	33331
0003	33332
0004	50001
	:
:	

Fig.7






Fig.8





FP03-0255-00

Fig.10





Fig.11



FP03-0255-00




Fig.13





Fig.14







Fig.16







Fig.18



FP03-0255-00

Fig.19A




Fig.19B





Fig. 20



21/29





Fig.22



FP03-0255-00






Fig. 23

Fig.24



25/29

Fig.25A






Fig. 26




Fig.27





Fig.28



FP03-0255-00

Fig.29A




Fig.29B




Fig.29C




Fig.29D

